



00036 13

The National Super Service Company
3115 Frenchmens Rd. □ TOLEDO, OHIO U.S.A. 43607-2958
PHONE: 419/531-2121 □ FAX: 419/531-3761

EPA Region 5 Records Ctr.



223113

MEMO

TO: Ralph Dollhopf
U.S. EPA Response Section 1
9311 Groh Road
Grosse Ile, Mi 48138-1697

REFERENCE NO. GRM 100397

DATE: October 3, 1997

FROM: Gary Mariucci
National Super Service

CC: Debra Orr, USEPA RPM
Ian Richardson, CRA

RE: Toledo Tie Treatment Site

As a follow-up to our meeting on October 1, 1997 (attended by USEPA, NSS, CRA, and E&E) and to confirm the voice mail message I left with you on October 1, 1997, NSS will install an oil boom in Williams Ditch directly upstream of the 36-inch storm sewer outfall. NSS will also maintain the boom around the 36-inch storm sewer outfall.

While NSS has agreed to have this work completed at this time, NSS only commits to inspecting and maintaining the boom across Williams Ditch for a period of 30 to 60 days. NSS's willingness to conduct this work should not be construed as an admission of liability on NSS's part for the oil sheen in Williams Ditch, but rather as a gesture of goodwill. In fact, based on our observations on October 1, 1997, it was clear that the primary source of the oil sheen in Williams Ditch is located upstream of the 36-inch storm sewer outfall.

The boom was put in place 10/2/97 by Philip Services. Should you have any questions please contact me at (419) 531-2121.

→ Flow



10/2/97 WILLIAMS DAM BOOM
PLACED BY NISS. AT REQUEST OF
EPP